

02475 Rosedale Rd.

Edgerton, OH 43517

e-mail: Brian@mavisconsulting.com



## Drainage Gravel Comparison Country Club

Brian Mavis

Phone: (419) 212-1639

[www.mavisconsulting.com](http://www.mavisconsulting.com)

*Drainage Gravel No Intermediate Layer*

*Intermediate Gravel Layer*

*Drainage Gravel with Intermediate Layer*

Date	Sample ID	<i>Drainage Gravel No Intermediate Layer</i>							<i>Intermediate Gravel Layer</i>							<i>Drainage Gravel with Intermediate Layer</i>																	
		12.5 mm	9.5 mm	6.3 mm	4.8 mm	2.4 mm	2.0 mm	1.0 mm	<1.0 mm	12.5 mm	9.5 mm	6.3 mm	4.8 mm	2.4 mm	2.0 mm	1.0 mm	<1.0 mm	12.5 mm	9.5 mm	6.3 mm	4.8 mm	2.4 mm	2.0 mm	1.0 mm	<1.0 mm								
	<i>USGA Guide</i>	0%						≤ 10%									≥ 90%									≥ 65%							≤ 10%
7/6/16	AIC Gravel 7-1-16	0	0	0	0.5	91.2	5	3.2		0	0	0.1	0.5	91	5	3.2																	
6/16/16	AIC Gravel 6-14-16	0	0	0	0.2	93.4	3.6	2.8		0	0	0	0.2	93	3.6	2.8																	
6/2/16	AIC Gravel 5-31-16	0	0	0	0.5	88.6	5.9	4.9		0	0	0	0.5	89	5.9	4.9																	
5/18/16	AIC Pre 5-16-16	0	0	0	1.3	89.1	4.4	4.6		0	0	0.1	1.3	89	4.4	4.6																	
5/18/16	AIC Delivered 5-16-16	0	0	0	1.4	85.4	6.4	6.4		0	0	0.2	1.4	85	6.4	6.4																	

**Comments:**

---

**Red indicates values of concern or not meeting USGA guidelines**

---